

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 25138	Main Street: CHAPEL_CREEK_CT			Cross	Street:	MEADOWRIDGE_DR	Location:	SE		
ADA ID: 29CD549D4C32	Ramp Type: Directional1			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
A CONTRACT OF A		Possible Solutions:			Compliance Description Data			Compliance Description Data		
A State A State A		Remove & Replace Entire	Ram	D.	N/A	Ramp Length (in)	30.0	N/A	Grade Break?	N/A
				· • ·	No	Ramp Width (in)	43.5	N/A	Grade Break Slope (%)	0.0
	JA.				Yes	Ramp Slope (%)	2.1	N/A	Grade Break XSlope (%)	0.0
June 2 - Sales / P	1				No	Ramp XSlope (%)	5.2			
CARE AND AND INC.	Mo E				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
A A A					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
A S		Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A CONTRACTOR	The second	N/A			N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
	CREED				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
	- Cop	2			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
	- Act	8			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
	N NE	PROW/ADA:			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
A TAKE A	Che Vite	R304.5.1, R304.5.3			N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	Y SAM				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
					N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
					N/A	Painted X Walk1?	No		Road Slope (%)	2.7
Street 1 Name CHAPEL	CREEK CT	-				X Walk 1 Direction	To NE		Road X Slope (%)	2.6
Stop Condition-Street 1	StopSign					X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A					X Walk 1 Slope (%)	2.7	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A					X Walk 1 X Slope (%)	2.6	N/A	Storm Grate/Utility Hazard?	N/A
					N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
					N/A	Any Obstructions?	N/A			N/A
		Total Cost:	\$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
							N/A	N/A	Curb Slope (%)	10.6

