


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                        |                             |                               |                        |
|------------------------|-----------------------------|-------------------------------|------------------------|
| Intersection ID: 30336 | Main Street: DULIN_CREEK_BV | Cross Street: FOUR_SISTERS_LN | Location: SE           |
| ADA ID: 29CDBFE3A1A0   | Ramp Type: PerpDiag         | Initial Pass/Fail: Fail       | Overall Compliance: No |
|                        |                             | Severity Score: 10            |                        |

| Codes/Mitigation Info/Possible Solution   |   |  | Field Measurements/Component Compliance |                          |             |
|---|---|--|---|--------------------------|-------------|
|                       | Possible Solutions:   |  | <b>Compliance</b>                       | <b>Description</b>       | <b>Data</b> |
|   | <b>Remove &amp; Replace Curb Ramp With Two New Directional Ramps or Equivalent.</b> |  | <b>Yes</b>                              | Ramp Length (in)         | 8.2         |
|   |   |  | <b>No</b>                               | Ramp Width (in)          | 3.6         |
|   |   |  | <b>N/A</b>                              | Flare Type LT            | N/A         |
|   |   |  | <b>N/A</b>                              | Flare Slope LT (%)       | N/A         |
|   |   |  | <b>N/A</b>                              | Flare Traversable LT?    | N/A         |
|   |   |  | <b>N/A</b>                              | Landing Length (in)      | N/A         |
|   |   |  | <b>N/A</b>                              | Landing Width (in)       | N/A         |
|   |   |  | <b>N/A</b>                              | Landing Slope (%)        | N/A         |
|   |   |  | <b>N/A</b>                              | Landing X Slope (%)      | N/A         |
|   |   |  | <b>N/A</b>                              | Landing Curb? (Y/N)      | N/A         |
|   |   |  | <b>N/A</b>                              | Shared Landing?          | N/A         |
|   |   |  | <b>N/A</b>                              | Gutter Ponding?          | N/A         |
|   |   |  | <b>N/A</b>                              | Gutter Lip Ht (in)       | N/A         |
|   |   |  | <b>No</b>                               | Painted X Walk1?         | No          |
|   |   |  |   | X Walk 1 Direction       | To N        |
|   |   |  | <b>N/A</b>                              | X Walk 1 Width (in)      | N/A         |
|   |   |  |   | X Walk 1 Slope (%)       | 3.1         |
|   |   |  |   | X Walk 1 X Slope (%)     | 3.6         |
|   |   |  | <b>N/A</b>                              | Ramp inside XWalk1?      | N/A         |
| <p>Surveyor Notes:</p> <p><b>N/A</b></p> <p>PROW/ADA:</p> <p><b>Not Found, R304.5.1, R304.5.3</b></p> |   |  | <b>N/A</b>                              | Ramp inside XWalk2?      | N/A         |
|   |   |  |   | Road Slope (%)           | 1.6         |
|   |   |  |   | Road X Slope (%)         | 2.3         |
|   |   |  | <b>N/A</b>                              | Any Obstructions?        | N/A         |
|   |   |  |   | Obstruction Type         |             |
|   |   |  | <b>N/A</b>                              |                          | N/A         |
|   |   |  | <b>Yes</b>                              | Surface Condition? (G/P) | Good        |
|   |   |  |   |                          |             |
|   |   |  |   |                          |             |
|   |   |  |   |                          |             |
|   |   |  |   |                          |             |
|   |   |  |   |                          |             |
|   |   |  |   |                          |             |
|   |   |  |   |                          |             |
|   |   |  |   |                          |             |
|   |   |  |   |                          |             |
|   |   |  |   |                          |             |
|   |   |  |   |                          |             |
|   |   |  |   |                          |             |
|   |   |  |   |                          |             |
|   |   |  |   |                          |             |
|   |   |  |   |                          |             |

|                         |                 |
|-------------------------|-----------------|
| Street 1 Name           | DULIN CREEK BV  |
| Stop Condition-Street 2 | None            |
| Street 2 Name           | FOUR SISTERS LN |
| Stop Condition-Street 1 | StopSign        |

Total Cost: \$ 3200.00

