cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12304 Ma	ain Street: COBBLERIDGE_DR	Cross Street	: SHAMROCK_DR			Location:	Ν	
ADA ID: 2A6AB53A98BD Ra	BD Ramp Type: PerpDiag		nitial Pass/Fail: Fail Overall Compliance			o Severity Score:	10	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:	Com					Data	
	Remove & Replace Curb Ramp W	/ith N/A	Ramp Length (in)	65.0	Yes	Ramp Slope (%)	6.9	
	Two New Directional Ramps or	No	Ramp Width (in)	40.0	No	Ramp XSlope (%)	2.1	
	Equivalent.	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	the state	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
E Partie	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
Store		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
A CONTRACTOR OF		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
E Contraction		N/A	Shared Landing?	N/A				
IN THE REAL PROPERTY OF	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
			X Walk 1 Direction	To SW		X Walk 2 Direction	To SE	
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name SHAMROO	CK DR		X Walk 1 Slope (%)	3.2		X Walk 2 Slope (%)	1.5	
Stop Condition-Street 2	None		X Walk 1 X Slope (%)	1.6		X Walk 2 X Slope (%)	0.4	
Street 2 Name COBBLERIDO	GE DR	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1 Sto	pSign		Road Slope (%)	6.6	N/A	Clear Space?	N/A	
			Road X Slope (%)	2.1	N/A	Clear Space to XWalk (in)	N/A	
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 32	200.00	Obstruction Type			Storm Grate/Utility Type		
				N/A			N/A	

Yes Surface Condition? (G/P)

Good

