

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 11524	Main Street: BOYER_ST	Cross Street: WILKINSON_BV	Location: SE
ADA ID: 2ABF5C7F4F60	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 5	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	98.0
	Remove & Replace Gutter.		Yes	Ramp Width (in)	69.0
			Yes	Flare Type L	Curbed_NoWalkSurface
			Yes	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	No
			Yes	Landing Length (in)	72.0
			Yes	Landing Width (in)	69.0
			Yes	Landing Slope (%)	1.7
			Yes	Landing X Slope (%)	1.4
Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.4			N/A	Landing Curb? (Y/N)	No
			N/A	Shared Landing?	No
			Yes	Gutter Ponding?	No
			Yes	Gutter Lip Ht (in)	0.0
			N/A	Painted X Walk1?	Yes
				X Walk 1 Direction	To NE
			N/A	X Walk 1 Width (in)	118.0
				X Walk 1 Slope (%)	1.6
				X Walk 1 X Slope (%)	5.1
			Yes	Ramp inside XWalk1?	Yes
				Road Slope (%)	N/A
				Road X Slope (%)	N/A
			Yes	Any Obstructions?	No
				Obstruction Type	
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good
Total Cost:		\$ 2600.00			

