

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

61.0

57.0

11.5

2.3

5.2

7.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

1.6

Intersection ID: 10037443 Main Street: SCOTT AV Cross Street: N/A S Location: Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 15 ADA ID: 2ACF04383103 Ramp Type: Combination2Diag

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

No

No

Yes

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

Curb Slope (%)

Flare Traversable RT?

Data

N/A

N/A

N/A

N/A

47.0

52.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)



Street 1 Name StopSign Stop Condition-Street 1 LOOP RD Street 2 Name None Stop Condition-Street 2 SCOTT AV Possible Solutions: Compliance Description N/A Remove & Replace Curb Ramp With Two New Directional Ramps or N/A Equivalent. N/A N/A N/A Yes Surveyor Notes: N/A N/A N/A N/A N/A N/A PROW/ADA: N/A R304.5.3, R304.3.2, R302.7 N/A N/A N/A N/A N/A N/A

Total Cost:



N/A

3200.00

Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A N/A Painted X Walk2? Painted X Walk1? Yes No To NE To NW X Walk 1 Direction X Walk 2 Direction X Walk 1 Width (in) 77.0 X Walk 2 Width (in) N/A 3.9 2.0 X Walk 1 Slope (%) X Walk 2 Slope (%) X Walk 1 X Slope (%) 5.6 X Walk 2 X Slope (%) 5.8 N/A Ramp inside XWalk1? Yes Ramp inside XWalk2? N/A Road Slope (%) 6.5 Clear Space? N/A Road X Slope (%) 1.3 N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A No Surface Condition? (G/P) Poor

