

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

2.3

3.7

N/A

Intersection ID: 52908 Main Street: FLAT BRANCH CLOSE RD Cross Street: CLEMS CROSSING DR Location: NE **Overall Compliance: No Severity Score:** 1.25 ADA ID: 2AF3A485D3B4 Ramp Type: BlendTrans1 Initial Pass/Fail: Fail

Compliance Description

N/A

Yes

N/A

N/A

N/A

N/A

N/A

N/A

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Gutter Lip Ht (in)

Painted X Walk1?

Flare Traversable LT?

Flare Type LT

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

No

N/A

Compliance Description

Flare Type RT

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

Flare Traversable RT?

BlendTrans Slope (%)

BlendTrans XSlope (%)

Data

120.0

100.0

N/A

No



FLAT BRANCH CLOSE RD Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

Possible Solutions:

N/A

PROW/ADA:

R304.5.3

Total Cost:

StopSign N/A N/A

N/A N/A N/A N/A N/A N/A N/A N/A 3200.00



X Walk 1 Direction To NW X Walk 2 Direction N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A X Walk 1 Slope (%) X Walk 2 Slope (%) N/A 7.4 X Walk 2 X Slope (%) X Walk 1 X Slope (%) 3.5 N/A N/A N/A Ramp inside XWalk2? Ramp inside XWalk1? N/A Road Slope (%) 3.5 Clear Space? N/A N/A Road X Slope (%) 7.4 Clear Space to XWalk (in) N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good N/A Curb Slope (%) 0.5



