

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

2.5

5.8

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: 13343 Main Street: E INDEPENDENCE BV **Cross Street: CHARLOTTETOWNE AV** Location: ADA ID: 2B0965C499D5 Ramp Type: BlendTrans1 Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 21.25

Compliance Description

N/A

No

N/A

N/A

N/A

N/A

N/A

N/A

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Flare Traversable LT?

Flare Type LT

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance Data

39.0 No

Yes

N/A

N/A

N/A

N/A

N/A

N/A N/A

60.0

N/A

N/A

N/A

N/A

N/A

Compliance Description

Flare Type RT

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

Flare Traversable RT?

BlendTrans Slope (%)

BlendTrans XSlope (%)



Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

N/A

	1	-
4.4		X
11		
A STATE OF THE STA		



	The state of the s									
	Colonia Colonia				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	10				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
					N/A	Shared Landing?	N/A			
		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Park State	Not Found, R304.5	i.1, R304.5.	3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	A TOTAL STATE OF THE PARTY OF T	,	•		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
(// L						X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
1 100000000000000000000000000000000000						X Walk 1 Width (in)	111.0		X Walk 2 Width (in)	N/A
Street 1 Name	CHARLOTTETOWNE AV					X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	Signal					X Walk 1 X Slope (%)	1.4		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A					Road Slope (%)	1.4		Clear Space?	N/A
						Road X Slope (%)	0.2	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A
								Yes	Surface Condition? (G/P)	Good
					· ·			No	Curb Slope (%)	13.2