

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 54660	Main Street: WISDOM_LN		Cross	Cross Street: BAUCOM_RD			Location: N		
ADA ID: 2B3B9DAC05A8			Initial Pass/Fail: Fail Overall Complian						
			minuari						
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance Compliance Description Data					
A MARKEN STATUS	A PAR	Possible Solutions:		Compliance Description					
	in and white	Remove & Replace Entire Ram	0.	N/A	Ramp Length (in)			Grade Break?	N/A
A CARLES AND A ME	an with			Yes	Ramp Width (in)	69.0	N/A	Grade Break Slope (%)	0.0
	1			No	Ramp Slope (%)		N/A	Grade Break XSlope (%)	0.0
				No	Ramp XSlope (%)	2.3			
A A A A A A A A A A A A A A A A A A A	a les			N/A	Flare Type LT	N/A		Flare Type RT	N/A
	Our			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
E The		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	The state of the s	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
	1 1 1			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
	Super . 1			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
	A LON			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
Contraction of	The state	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
- 68 march	A Part of the Part	R304.2.2, R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	1964	,		N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
	1 23			N/A	Painted X Walk1?	No		Road Slope (%)	3.9
Street 1 Name	WISDOM LN	-			X Walk 1 Direction	To SE		Road X Slope (%)	0.4
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	3.9	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	0.4	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	N/A

