

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

N/A

N/A

N/A

N/A

5.8

5.7

N/A

No

N/A

3.7

4.1

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Good 11.8

To SW

Intersection ID: 20051 Main Street: ARCHDALE_DR Cross Street: BURNLEY_RD Location: E

ADA ID: 2B52D44C1D28 Ramp Type: Combination2Diag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 0

Compliance Description

Road Slope (%)

Road X Slope (%)

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Data



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

StopSign BURNLEY RD None ARCHDALE RD Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.3, R304.3.2

Total Cost:

N/A N/A Ramp Length LT (in) 45.5 Ramp Length RT (in) 72.0 N/A Yes Ramp Width LT (in) Ramp Width RT (in) 12.7 N/A No Ramp Slope LT (%) Ramp Slope RT (%) Ramp XSlope LT (%) 2.3 N/A Ramp XSlope RT (%) No N/A Ramp Length (in) 39.0 Yes Ramp Slope (%) 48.0 No Ramp XSlope (%) Yes Ramp Width (in) N/A Flare Type LT N/A N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A Flare Slope RT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A **DWS Contrast?** N/A Landing Width (in) N/A Landing Slope (%) N/A N/A DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A Shared Landing? N/A N/A Gutter Ponding? N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No Painted X Walk2? To NW X Walk 1 Direction X Walk 2 Direction X Walk 1 Width (in) N/A X Walk 2 Width (in) 4.5 X Walk 1 Slope (%) X Walk 2 Slope (%) X Walk 1 X Slope (%) 4.1 X Walk 2 X Slope (%) N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2?

5.3

2.3

N/A

N/A

N/A

Yes

Clear Space?

Any Obstruction?

Obstruction Type

Curb Slope (%)

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)







3200.00