

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A	Main Str	Main Street: PRINCETON_AV			Cross Street: SOMERSET_DR				NW
ADA ID: 2B6E43610396	Ramp Ty	Ramp Type: Directional2		Initial Pass/Fail: Fail Overall Compliance			ice: N	o Severity Score:	1.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:					Compliance Description Data		
Mart - School Real	THE PART	Remove & Replace Entire Rai	nn	N/A	Ramp Length (in)	67.0	N/A	Grade Break?	N/A
	A			Yes	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0
	THE CHILD			Yes	Ramp Slope (%)	1.5	N/A	Grade Break XSlope (%)	0.0
	HEROMAN OF			No	Ramp XSlope (%)	2.9			
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
1		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
PRINCETION AND		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
		1071		N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
HAN			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
	Pielo Lin Li	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
		R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	P-SAC	1004.0.0		N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No		Road Slope (%)	4.0
Street 1 Name	SOMERSET DR	-			X Walk 1 Direction	To E		Road X Slope (%)	1.5
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	. C N/A				X Walk 1 Slope (%)	4.0	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	1.5	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1800.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	1.5

