


Intersection ID: 11139		Main Street: EVERETT_PL		Cross Street: PARSON_ST		Location:		SE	
ADA ID: 2B71A717E2C3		Ramp Type: Perp		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 12.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance		Description		Data	
		Remove & Replace Entire Ramp.		N/A		Ramp Length (in)		56.0	
				Yes		Ramp Width (in)		48.0	
				N/A		Flare Type LT		N/A	
				N/A		Flare Slope LT (%)		N/A	
				N/A		Flare Traversable LT?		N/A	
				N/A		Landing Length (in)		N/A	
				N/A		Landing Width (in)		N/A	
				N/A		Landing Slope (%)		N/A	
				N/A		Landing X Slope (%)		N/A	
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.2.2</p>				N/A		Flare Slope RT (%)		N/A	
				N/A		Flare Traversable RT?		N/A	
				N/A		DWS Provided?		N/A	
				N/A		DWS Contrast?		N/A	
				N/A		DWS Length (in)		N/A	
				N/A		DWS Full Width?		N/A	
				N/A		DWS Offset (in)		N/A	
				N/A					
				N/A		Gutter Ponding?		N/A	
				N/A		Gutter Lip Ht (in)		N/A	
		N/A		Painted X Walk1?		No			
				X Walk 1 Direction		To W			
		N/A		X Walk 1 Width (in)		N/A			
				X Walk 1 Slope (%)		1.8			
				X Walk 1 X Slope (%)		2.1			
		N/A		Ramp inside XWalk1?		N/A			
				Road Slope (%)		N/A			
				Road X Slope (%)		N/A			
		N/A		Any Obstructions?		N/A			
				Obstruction Type					
						N/A			
						Yes			
						Surface Condition? (G/P)			
						Good			

