

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

| Intersection ID: 20840 | 0840 Main Street: SARDIS_LN | | | | Stroot. | | Location: | SW | | |
|---|-----------------------------|----------------------|--|---|---------------------|-----------------------|-----------|-----------------------------|-----------------------------|-----|
| | | | | Cross Street: SARDIS_RD | | | | | | |
| ADA ID: 2BC3641E6282 Ramp Type: Perp | | | Initial Pass/Fail: Fail Overall Compliance: No | | | | | o Severity Score: | 21.25 | |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | | |
| | | Possible Solutions: | | Compliance Description | | | Data | Data Compliance Description | | |
| | | Remove & Replace En | tire Ramp | | N/A | Ramp Length (in) | 51.0 | No | Ramp Slope (%) | 8.7 |
| | | | | | No | Ramp Width (in) | 44.0 | Yes | Ramp XSlope (%) | 0.9 |
| | | | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | | | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | | | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| KLL EIGTAG | | | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | | Surveyor Notes: | | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | | N/A | | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | | | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| A Carlo and a carlo and a carlo | To Stre | | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| 14 A. | | | | | N/A | Shared Landing? | N/A | | | |
| | | PROW/ADA: | | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| A AND AND AND A | | Not Found, R304.5.1, | R304.2.2 | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| And Here and | | | | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A |
| A A A A A A A A A A A A A A A A A A A | | | | | | X Walk 1 Direction | To E | | X Walk 2 Direction | N/A |
| | | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A | |
| Street 1 Name | SARDIS RD | | | | | X Walk 1 Slope (%) | 0.9 | | X Walk 2 Slope (%) | N/A |
| Stop Condition-Street 2 | None | | | | | X Walk 1 X Slope (%) | 2.0 | | X Walk 2 X Slope (%) | N/A |
| Street 2 Name | N/A | | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | N/A | | | | | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| | | | | | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| | | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | Total Cost: | \$ | 850.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | | | N/A | | | N/A |

