

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

9.5

60.0

6.5

4.3

N/A

Good 19.3

Intersection ID: 48944 Main Street: LILLYSHIRE PL Cross Street: CALDWELL RIDGE PY Location: SW **Severity Score:** 10 ADA ID: 2BE1CDEA5592 Ramp Type: Combination1 Initial Pass/Fail: Fail **Overall Compliance: No**

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

Yes

No

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Data

2.0

59.5

2.7

3.1

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp XSlope LT (%)



Street 1 Name StopSign Stop Condition-Street 1 LILLYSHIRE PL N/A Street 2 Name Stop Condition-Street 2 N/A Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. Yes Yes No No Surveyor Notes: LT RP < 5% PROW/ADA: Not Found, R304.5.1, R304.5.3

Total Cost:



1800.00

N/A Ramp Length (in) 46.5 Yes Ramp Slope (%) 2.6 43.0 No Ramp XSlope (%) 2.3 Ramp Width (in) N/A Flare Type LT N/A N/A Flare Type RT N/A N/A N/A N/A Flare Slope LT (%) Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A N/A **DWS Contrast?** N/A Landing Width (in) N/A N/A Landing Slope (%) N/A N/A DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? N/A N/A Gutter Ponding? N/A N/A Gutter Slope (%) N/A N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A N/A N/A Painted X Walk1? No Painted X Walk2? N/A To N N/A X Walk 1 Direction X Walk 2 Direction X Walk 1 Width (in) N/A X Walk 2 Width (in) N/A 4.2 N/A X Walk 1 Slope (%) X Walk 2 Slope (%) X Walk 1 X Slope (%) 0.7 X Walk 2 X Slope (%) N/A N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2? N/A Road Slope (%) N/A Clear Space? N/A Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type

Yes

Surface Condition? (G/P)

Curb Slope (%)

