

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                        |                          |                          |                        |
|------------------------|--------------------------|--------------------------|------------------------|
| Intersection ID: 17633 | Main Street: NORMANDY_RD | Cross Street: ROSWELL_AV | Location: NE           |
| ADA ID: 2C6300804DFD   | Ramp Type: Directional1  | Initial Pass/Fail: Fail  | Overall Compliance: No |
|                        |                          |                          | Severity Score: 21.25  |

| Codes/Mitigation Info/Possible Solution                                          |                               |            | Field Measurements/Component Compliance |                       |       |            |                             |      |
|----------------------------------------------------------------------------------|-------------------------------|------------|-----------------------------------------|-----------------------|-------|------------|-----------------------------|------|
|  | Possible Solutions:           |            | Compliance                              | Description           | Data  | Compliance | Description                 | Data |
|                                                                                  | Remove & Replace Entire Ramp. |            | N/A                                     | Ramp Length (in)      | 108.0 | N/A        | Grade Break?                | N/A  |
|                                                                                  |                               |            | No                                      | Ramp Width (in)       | 42.0  | N/A        | Grade Break Slope (%)       | 0.0  |
|                                                                                  |                               |            | No                                      | Ramp Slope (%)        | 8.5   | N/A        | Grade Break XSlope (%)      | 0.0  |
|                                                                                  |                               |            | Yes                                     | Ramp XSlope (%)       | 1.1   |            |                             |      |
|                                                                                  |                               |            | N/A                                     | Flare Type LT         | N/A   | N/A        | Flare Type RT               | N/A  |
|                                                                                  |                               |            | N/A                                     | Flare Slope LT (%)    | N/A   | N/A        | Flare Slope RT (%)          | 0.0  |
|                                                                                  |                               |            | N/A                                     | Flare Traversable LT? | N/A   | N/A        | Flare Traversable RT?       | N/A  |
|                                                                                  | Surveyor Notes:               |            | N/A                                     | Landing Length (in)   | 0.0   | N/A        | DWS Provided?               | N/A  |
|                                                                                  |                               |            | N/A                                     | Landing Width (in)    | 0.0   | N/A        | DWS Contrast?               | N/A  |
|                                                                                  |                               |            | N/A                                     | Landing Slope (%)     | 0.0   | N/A        | DWS Length (in)             | N/A  |
|                                                                                  |                               |            | N/A                                     | Landing X Slope (%)   | 0.0   | N/A        | DWS Full Width?             | N/A  |
|                                                                                  | PROW/ADA:                     |            | N/A                                     | Landing Curb? (Y/N)   | N/A   | N/A        | DWS Offset LT (in)          | N/A  |
|                                                                                  | R304.5.1, R304.2.2            |            | N/A                                     | Shared Landing?       | N/A   | N/A        | DWS Offset RT (in)          | N/A  |
|                                                                                  |                               |            | N/A                                     | Gutter Ponding?       | 0.0   | N/A        | Gutter Slope (%)            | N/A  |
|                                                                                  |                               |            | N/A                                     | Gutter Lip Ht (in)    | 0.0   | N/A        | Gutter X Slope (%)          | N/A  |
|                                                                                  |                               |            | N/A                                     | Painted X Walk1?      | No    |            | Road Slope (%)              | 3.3  |
|                                                                                  |                               |            |                                         | X Walk 1 Direction    | To S  |            | Road X Slope (%)            | 3.9  |
|                                                                                  |                               |            |                                         | X Walk 1 Width (in)   | N/A   |            | Clear Space?                | N/A  |
|                                                                                  |                               |            |                                         | X Walk 1 Slope (%)    | 3.3   | N/A        | Clear Space to XWalk (in)   | N/A  |
|                                                                                  |                               |            |                                         | X Walk 1 X Slope (%)  | 3.9   | N/A        | Storm Grate/Utility Hazard? | N/A  |
|                                                                                  |                               |            | N/A                                     | Ramp inside XWalk1?   | N/A   |            | Storm Grate/Utility Type    |      |
|                                                                                  |                               |            | N/A                                     | Any Obstructions?     | N/A   |            |                             | N/A  |
|                                                                                  |                               |            |                                         | Obstruction Type      |       | Yes        | Surface Condition? (G/P)    | Good |
|                                                                                  |                               |            |                                         |                       |       | N/A        | Curb Slope (%)              | 11.4 |
| Total Cost:                                                                      |                               | \$ 1600.00 |                                         |                       |       |            |                             |      |

|                         |             |
|-------------------------|-------------|
| Street 1 Name           | NORMANDY RD |
| Stop Condition-Street 1 | StopSign    |
| Street 2 Name           | N/A         |
| Stop Condition-Street 2 | N/A         |

Total Cost: \$ 1600.00

