

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 24455 Main Street: S_TRYON_ST				eet.	STEELE_CREEK_RD	Location:	NW		
ADA ID: 2C7F65EC3FF7 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No					o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
1 1 10 1 1 1 1 1 1 1		Possible Solutions:	Compliance Description			Data	Data Compliance Description		
- / / / / -		Remove & Replace Entire Ramp	. N/	/ A	Ramp Length (in)	95.0	No	Ramp Slope (%)	8.6
	C G G		Ye	es	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.4
13	13 8		N/	/ A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	ar B		N	/ A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	9		N	/ A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N	/ A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
C A State A State	1 and 1 and 1	Surveyor Notes:	N	/ A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
M. A. A.		N/A	N	/ A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N	/ A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	13		N	/ A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
A Calor	A A		N	/ A	Shared Landing?	N/A			
3	× 100-	PROW/ADA:	N	/ A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
11/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1	6 AN	Not Found, R304.2.2, R304.5.3	N/	/ A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
11 11	2/ 10/ 1		N	/ A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
1 1 Star	6. B				X Walk 1 Direction	To S		X Walk 2 Direction	N/A
			N	/ A	X Walk 1 Width (in)	129.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	S TRYON ST				X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	0.5		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N	/ A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N	/ A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

