
cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



									014/
Intersection ID: 11439	Main Street: HILLIARD_DR		Cross	Cross Street: JEFF_ST				Location:	SW
ADA ID: 2CC81494070A	Ramp Type: BlendTrans2			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		Data
		Remove & Replace Curb Ramp V Two New Directional Ramps or Equivalent.	p With	N/A	Ramp Length (in)	49.0	Yes	BlendTrans Slope (%)	3.5
				Yes	Ramp Width (in)	50.0	No	BlendTrans XSlope (%)	5.2
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
MILLING				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
DR		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	- E			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Table 1 and a state	a the way			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	20-1-12			N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
A REAL PROPERTY OF	10 m			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
the the second second	22				X Walk 1 Direction	To E		X Walk 2 Direction	N/A
the she was a low	111				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	JEFF ST				X Walk 1 Slope (%)	6.3		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	6.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	6.0		Clear Space?	N/A
					Road X Slope (%)	6.3	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A



Good

12.0



