

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

27.0

48.0

2.9

1.9

5.8

3.8

N/A

No

N/A

0.9

4.2

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Good 9.4

To NW

Intersection ID: 45508 Main Street: MEADOW_BOTTOM_RD Cross Street: WHEATFIELD_RD Location: SW

ADA ID: 2CC962D64B4F Ramp Type: Combination1Diag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 0

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

None MEADOW BOTTOM RD StopSign WHEATFIELD RD Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

RT RP < 5%

PROW/ADA:

Not Found, R304.5.1, R304.5.1, R304.5.3

Total Cost:

Compliance Description Data Compliance Description N/A Ramp Length RT (in) N/A Ramp Length LT (in) 30.0 47.0 Yes No Ramp Width LT (in) Ramp Width RT (in) Yes Yes Ramp Slope LT (%) 7.3 Ramp Slope RT (%) Ramp XSlope LT (%) Yes Ramp XSlope RT (%) Yes 1.9 N/A Ramp Length (in) 71.0 Yes Ramp Slope (%) 45.0 No Ramp XSlope (%) No Ramp Width (in) N/A Flare Type LT N/A N/A Flare Type RT N/A N/A N/A Flare Slope LT (%) Flare Slope RT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A N/A Landing Width (in) **DWS Contrast?** N/A Landing Slope (%) N/A N/A DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A Shared Landing? N/A N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No Painted X Walk2? To NE X Walk 1 Direction X Walk 2 Direction X Walk 1 Width (in) N/A X Walk 2 Width (in) 3.2 X Walk 1 Slope (%) X Walk 2 Slope (%) X Walk 1 X Slope (%) 1.5 X Walk 2 X Slope (%) N/A N/A Ramp inside XWalk1? N/A Ramp inside XWalk2? Road Slope (%) 3.0 Clear Space?

3.5

N/A

N/A

N/A

Yes

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Any Obstruction?

Obstruction Type

Curb Slope (%)







3200.00