

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10025500 Main Street: E_MARTIN_LUTHER_KING_JR_OBVss Street: N/A Location: S

Ramp Type: Directional1 **Overall Compliance: No** 25 ADA ID: 2D108462FE62 Initial Pass/Fail: Fail **Severity Score:**

Codes/Mitigation Info/Possible Solution



	8	
Street 1 Name		ENTRANCE
Stop Condition-Street	: 1	None
Street 2 Name		N/A
Ston Condition-Street	. 2	N/A

	Possible Solutions:
	Remove & Replace Entire Ramp.
ı	
ı	
-	
•	
	Surveyor Notes:
	N/A
ì	
4	PROW/ADA:
ξ	R304.5.3
4	

Total Cost:	\$ 1600.00

Field Measurements/Component Compliance								
Comp	liance Description	Data	Comp	liance Description	Data			
N/A	Ramp Length (in)	80.0	N/A	Grade Break?	N/A			
Yes	Ramp Width (in)	95.0	N/A	Grade Break Slope (%)	0.0			
Yes	Ramp Slope (%)	1.2	N/A	Grade Break XSlope (%)	0.0			
No	Ramp XSlope (%)	7.6						
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A			
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0			
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A			
N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A			
N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A			
N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A			
N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A			
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A			
N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A			
N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A			
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A			
N/A	Painted X Walk1?	No		Road Slope (%)	4.6			
	X Walk 1 Direction	To NW		Road X Slope (%)	7.6			
	X Walk 1 Width (in)	N/A		Clear Space?	N/A			
	X Walk 1 Slope (%)	4.6	N/A	Clear Space to XWalk (in)	N/A			
	X Walk 1 X Slope (%)	7.6	N/A	Storm Grate/Utility Hazard?	N/A			
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type				
N/A	Any Obstructions?	N/A			N/A			
	Obstruction Type		Yes	Surface Condition? (G/P)	Good			
		N/A	N/A	Curb Slope (%)	8.3			
			=					





