

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 42493	Main Street: REA_RD			Street:	TOLLESON_AV	Location:	NW		
ADA ID: 2D3B217BEF5B	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:						liance Description	Data
		Remove & Replace Entire Ram	<b>n</b>	N/A	Ramp Length (in)	70.0	No	Ramp Slope (%)	11.1
	A. C.	Remove & Replace Entire Ran	ip.	No	Ramp Width (in)	40.0	Yes	Ramp XSlope (%)	0.8
	No. Contraction			N/A	Flare Type LT	 N/A	N/A	Flare Type RT	N/A
and the first 1 1 1 1 1 1	KIL CL	ê		N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A
	0 4				,		N/A	,	
				N/A	Flare Traversable LT?	N/A		Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	S NESON	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	TOL	N/A		N/A	Landing Slope (%)	N/A		DWS Length (in)	N/A
	1 1 1 1			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
1999 2 L				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
the second secon	11.18	*		N/A	Shared Landing?	N/A			
	5 41	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		R304.5.1, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
- TETTINE STATE				X Walk 1 Direction	To SE		X Walk 2 Direction	N/A	
	1		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name T	OLLESON AV				X Walk 1 Slope (%)	1.0		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	0.7		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
		ισται σοστ. ψ				N/A		Com Oraco, Ouncy Type	N/A
						N/A			N/A

Yes Surface Condition? (G/P)

Good





