

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 27766 Main Street: BLAKENEY\_HEATH\_RD Cross Street: BRYANT\_FARMS\_RD Location: Severity Score: **Overall Compliance: No ADA ID: 2DB6F96DB712** Ramp Type: Directional1 Initial Pass/Fail: Fail 1.25

**Codes/Mitigation Info/Possible Solution** 



Street 1 Name	<b>BLAKENEY HEATH RD</b>
Stop Condition-Street 1	StopSign
Street 2 Name	N/A
Stop Condition-Street 2	N/A

Possible Solutions:	
Remove & Replace Entire Ramp.	
Surveyor Notes:	
N/A	
PROW/ADA:	
R304.5.3	
1004.5.5	

R304.5.3	
Total Cost:	\$ 1600.00

Field Measurements/Component Compliance									
Compli	iance	Description	Data	Com	pliance	Description	Data		
N/A	Ramp	Length (in)	47.0	N/A	Grad	e Break?	N/A		
Yes	Ramp	Width (in)	57.0	N/A	Grad	e Break Slope (%)	0.0		
Yes	Ramp	Slope (%)	5.1	N/A	Grad	e Break XSlope (%)	0.0		
No	Ramp	XSlope (%)	4.5						
N/A	Flare	Type LT	N/A	N/A	Flare	Type RT	N/A		
N/A	Flare	Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	0.0		
N/A	Flare	Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A		
N/A	Landi	ng Length (in)	0.0	N/A	DWS	Provided?	N/A		
N/A	Landi	ng Width (in)	0.0	N/A	DWS	Contrast?	N/A		
N/A	Landi	ng Slope (%)	0.0	N/A	DWS	Length (in)	N/A		
N/A	Landi	ng X Slope (%)	0.0	N/A	DWS	Full Width?	N/A		
N/A	Landi	ng Curb? (Y/N)	N/A	N/A	DWS	Offset LT (in)	N/A		
N/A	Share	ed Landing?	N/A	N/A	DWS	Offset RT (in)	N/A		
N/A	Gutte	r Ponding?	0.0	N/A	Gutte	er Slope (%)	N/A		
N/A	Gutte	r Lip Ht (in)	0.0	N/A	Gutte	er X Slope (%)	N/A		
N/A	Painte	ed X Walk1?	No		Road	l Slope (%)	1.9		
	X Wal	k 1 Direction	To NE		Road	I X Slope (%)	6.4		
	X Wal	k 1 Width (in)	N/A		Clea	r Space?	N/A		
	X Wal	k 1 Slope (%)	1.9	N/A	Clea	r Space to XWalk (in)	N/A		
	X Wal	k 1 X Slope (%)	6.4	N/A	Storr	n Grate/Utility Hazard?	N/A		
N/A	Ramp	inside XWalk1?	N/A		Storr	n Grate/Utility Type			
N/A	Any C	bstructions?	N/A				N/A		
	Obstr	uction Type		Yes	Surfa	ace Condition? (G/P)	Good		
			N/A	N/A	Curb	Slope (%)	0.6		





