


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 46694	Main Street: TROTTERS RIDGE RD	Cross Street: OLD MEADOW RD	Location: SE
ADA ID: 2DD590CFD562	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 8.75	

Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance					
	Possible Solutions:						
	<b>Remove &amp; Replace Curb Ramp With Two New Directional Ramps or Equivalent.</b>	N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	7.8
		No	Ramp Width (in)	44.0	Yes	Ramp XSlope (%)	1.8
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		N/A	Shared Landing?	N/A			
		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
			X Walk 1 Direction	To N		X Walk 2 Direction	To W
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
			X Walk 1 Slope (%)	5.0		X Walk 2 Slope (%)	2.3
			X Walk 1 X Slope (%)	2.3		X Walk 2 X Slope (%)	4.1
		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
<p>Surveyor Notes:</p> <p><b>N/A</b></p>			Road Slope (%)	1.4	N/A	Clear Space?	N/A
			Road X Slope (%)	5.7	N/A	Clear Space to XWalk (in)	N/A
<p>PROW/ADA:</p> <p><b>Not Found, R304.5.1</b></p>		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
			Obstruction Type			Storm Grate/Utility Type	
					N/A		N/A
					Yes	Surface Condition? (G/P)	Good
<p>Street 1 Name OLD MEADOW RD</p> <p>Stop Condition-Street 2 StopSign</p> <p>Street 2 Name TROTTERS RIDGE RD</p> <p>Stop Condition-Street 1 None</p>							
<p>Total Cost: \$ 3200.00</p>							

