## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A	Main Street: TAMARACK DR				SINGLELEAF LN	Location:	W			
ADA ID: 2DE361ACB49D Ramp Type: Perp			Initial Pa	Initial Pass/Fail: Pass Overall Compliance: No				o Severity Score:	0	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	N 73	Possible Solutions:		Compliance Description			Data Compliance Description			
the set of the set	at the	Remove & Replace Entire Ramp	).	N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	6.6	
		Remove & Replace Gutter.		Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.9	
				N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A	
	* /	1		N/A	Flare Slope LT (%)	6.2	N/A	Flare Slope RT (%)	2.4	
				N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No	
				Yes	Landing Length (in)	48.0	Yes	DWS Provided?	Yes	
	100	Surveyor Notes:		Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes	
		N/A		Yes	Landing Slope (%)	1.9	Yes	DWS Length (in)	24.0	
				Yes	Landing X Slope (%)	0.6	Yes	DWS Full Width?	Yes	
A A A A A A A A A A A A A A A A A A A	1 Aler			N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	5.5	
A COLORED CONTRACT			N/A	Shared Landing?	No					
		PROW/ADA:		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.1	
		Not Found, R305.2, R304.5.3		Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	4.1	
		,,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
					X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name TAI	MARACK DR				X Walk 1 Slope (%)	1.6		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	2.7		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	No	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	Yes	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No	
		Total Cost: \$	2600.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

Yes Surface Condition? (G/P)

Good

