

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14678 Main Street: E_W_T_HARRIS_BV Cross Street: WALLACE_AV Location: SE

ADA ID: 2DF0C7FD1817 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name E W T HARRIS BV
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

Total Cost: \$ 1850.00

Dat	nce Description	Comp	Data	liance Description	Comp
8.	Ramp Slope (%)	No	60.0	Ramp Length (in)	N/A
0.	Ramp XSlope (%)	Yes	40.0	Ramp Width (in)	No
N/	Flare Type RT	N/A	N/A	Flare Type LT	N/A
N/	Flare Slope RT (%)	N/A	N/A	Flare Slope LT (%)	N/A
N/	Flare Traversable RT?	N/A	N/A	Flare Traversable LT?	N/A
N/	DWS Provided?	N/A	N/A	Landing Length (in)	N/A
N/	DWS Contrast?	N/A	N/A	Landing Width (in)	N/A
N/	DWS Length (in)	N/A	N/A	Landing Slope (%)	N/A
N/	DWS Full Width?	N/A	N/A	Landing X Slope (%)	N/A
N/	DWS Offset (in)	N/A	N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	N/A
N/	Gutter Slope (%)	N/A	N/A	Gutter Ponding?	N/A
N/	Gutter X Slope (%)	N/A	N/A	Gutter Lip Ht (in)	N/A
N/	Painted X Walk2?	N/A	No	Painted X Walk1?	N/A
N/	X Walk 2 Direction		To W	X Walk 1 Direction	
N/	X Walk 2 Width (in)	N/A	N/A	X Walk 1 Width (in)	N/A
N/	X Walk 2 Slope (%)		2.3	X Walk 1 Slope (%)	
N/	X Walk 2 X Slope (%)		0.8	X Walk 1 X Slope (%)	
N/	Ramp inside XWalk2?	N/A	N/A	Ramp inside XWalk1?	N/A
N/	Clear Space?	N/A	N/A	Road Slope (%)	
N/	Clear Space to XWalk (in)	N/A	N/A	Road X Slope (%)	
N/	Storm Grate/Utility Hazard?	N/A	N/A	Any Obstructions?	N/A
	Storm Grate/Utility Type			Obstruction Type	
N/			N/A		
Goo	Surface Condition? (G/P)	Yes			





