

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 19071 Main Street: S TRYON ST Cross Street: LAND GRANT RD NE Location: **Overall Compliance: No Severity Score:** 0 ADA ID: 2E88230733A3 Ramp Type: Combination1Diag Initial Pass/Fail: Fail

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2

StopSign LAND GRANT RD None S TRYON ST Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.2.2, R304.3.2, R304.5.3

Total Cost:



Any Obstruction?

Obstruction Type

Curb Slope (%)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

Yes

N/A

N/A

N/A

N/A

Good 7.3







3200.00