

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 16159 Main Street: HOLLIS RD **Cross Street: SLOAN\_ST** Location: N **Overall Compliance: No** ADA ID: 2EECD8E0C414 Ramp Type: Perp Initial Pass/Fail: Pass **Severity Score:** 0.25

**Codes/Mitigation Info/Possible Solution** 



THE RESERVE AND ASSESSMENT OF THE PARTY OF T	THE RESERVE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TW
Street 1 Name	HOLLIS RD
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions: Remove & Replace Entire Ramp. Remove & Replace Gutter. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.3, R304.2.1, R304.2.2-Perp, R304.3.2-Para

Total Cost:	\$ 2600.00	

Field Measurements/Component Compliance						
Comp	liance Description	Data	Comp	liance Description	Data	
N/A	Ramp Length (in)	60.0	Yes	Ramp Slope (%)	6.1	
Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	4.9	
N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	6.2	Yes	Flare Slope RT (%)	0.2	
N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes	
Yes	Landing Length (in)	52.0	Yes	DWS Provided?	Yes	
No	Landing Width (in)	47.5	Yes	DWS Contrast?	Yes	
No	Landing Slope (%)	2.1	Yes	DWS Length (in)	25.0	
Yes	Landing X Slope (%)	2.6	Yes	DWS Full Width?	Yes	
N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	0.0	
N/A	Shared Landing?	No				
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.7	
Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	4.3	
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	3.8		X Walk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	4.0		X Walk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear Space?	Yes	
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
			Yes	Surface Condition? (G/P)	Good	





