

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14381Main Street: CARLTON\_AVCross Street: ROMANY\_RDLocation:NEADA ID: 2F14877E76F8Ramp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 12.5

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name CARLTON AV
Stop Condition-Street 2 StopSign
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:

Remove & Replace Entire Ramp.

N

N

N

Surveyor Notes:

N/A

N

PROW/ADA:

Not Found, R304.5.3

Total Cost: \$ 1850.00

Field Measurements/Component Compliance						
Compliance Description			Data	Compliance Description		Data
N	I/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	7.5
Υ	'es	Ramp Width (in)	48.0	No	Ramp XSlope (%)	6.4
N	l/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N	I/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N	I/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N	I/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N	I/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N	I/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N	I/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N	I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N	I/A	Shared Landing?	N/A			
N	I/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N	l/A	Gutter Lip Ht (in)	2.0	N/A	Gutter X Slope (%)	N/A
N	I/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
		X Walk 1 Direction	To W		X Walk 2 Direction	N/A
N	I/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	6.2		X Walk 2 Slope (%)	N/A
		X Walk 1 X Slope (%)	0.3		X Walk 2 X Slope (%)	N/A
N	I/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	N/A	N/A	Clear Space?	N/A
		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
N	I/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Obstruction Type			Storm Grate/Utility Type	
			N/A			N/A
				Yes	Surface Condition? (G/P)	Good





