

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

Intersection ID: 28744 Main Street: PLEASANT_PLAINS_RD Cross Street: SAVANNAH_HILLS_DR Location: SW

ADA ID: 2F29FEBEAB30 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 10

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Data



Street 1 Name
PLEASANT PLAINS RD
Stop Condition-Street 2
None
Street 2 Name
N/A
Stop Condition-Street 1
N/A

Possible Solutions:

Remove & Replace Entire Ramp.

N/A Ramp Length (in)
No Ramp Width (in)
N/A Flare Type LT
N/A Flare Slope LT (%)
N/A Landing Length (in)
N/A Landing Length (in)
N/A Landing Slope (%)
N/A Landing Width (in)
N/A Landing Slope (%)
N/A Landing X Slope (%)
N/A Landing Curb? (Y/N
N/A Shared Landing?

PROW/ADA:

Not Found, R304.5.1, R304.5.3

N/A Gutter Ponding?

N/A Gutter Lip Ht (in)
N/A Painted X Walk 1?
X Walk 1 Direction
N/A X Walk 1 Slope (%)

Yes N/A Ramp Length (in) 49.0 Ramp Slope (%) 7.0 40.5 No Ramp XSlope (%) No Ramp Width (in) 2.9 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A Landing Length (in) N/A N/A **DWS Provided?** N/A N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? N/A X Walk 1 Direction To N X Walk 2 Direction N/A N/A N/A X Walk 2 Width (in) X Walk 1 Width (in) N/A N/A X Walk 1 Slope (%) 4.7 X Walk 2 Slope (%) N/A X Walk 1 X Slope (%) 1.2 X Walk 2 X Slope (%) N/A N/A N/A N/A Ramp inside XWalk2? Ramp inside XWalk1? N/A Road Slope (%) N/A N/A Clear Space? N/A N/A Road X Slope (%) N/A Clear Space to XWalk (in) N/A N/A N/A Any Obstructions? N/A Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good





Total Cost:



1850.00