cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10017066	6 Main Street: NEAL_RD		Cross Street: N/A					Location:	Е
ADA ID: 2F39BD50D9E6	Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliance:			nce: N	o Severity Score:	46.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:						Compliance Description	
		Remove & Replace Curb Ramp	/ith	N/A	Ramp Length (in)	76.0	No	Ramp Slope (%)	10.4
		Two New Directional Ramps or		No	Ramp Width (in)	39.0	No	Ramp XSlope (%)	8.2
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
8	Carlos /			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
the second		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
A starting the second s		R304.5.1, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	NEAL RD				X Walk 1 Slope (%)	10.7		X Walk 2 Slope (%)	6.1
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	14.2
Street 2 Name	ENTRANCE			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	5.6	N/A	Clear Space?	N/A
					Road X Slope (%)	11.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

es Surface Condition? (G/P)

Good

