

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 3559	Main Street: PERIMETER_PY			Cross Street: W_W_T_HARRIS_BV				Location:	NE
ADA ID: 2FC4FF5E72E1	DA ID: 2FC4FF5E72E1 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	2.	Possible Solutions:		Compliance Description			Data Compliance Description		
	31.1	Remove & Replace Entire Ra	np.	N/A	Ramp Length (in)	96.0	Yes	Ramp Slope (%)	7.0
	A		•	No	Ramp Width (in)	47.5	No	Ramp XSlope (%)	5.2
	200			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
HIT NOT				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Ser -	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
ANIA B		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
5 IN THE PROPERTY IS	100			N/A	Shared Landing?	N/A			
T L'ABINE	1	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	0	Not Found, R304.5.1, R304.5.	3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
	-				X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	118.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name WWTHA	RRIS BV				X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	YieldSign				X Walk 1 X Slope (%)	3.4		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

