

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

Yes

1.1

0.6

N/A

N/A

No

Yes

Yes

24.0

No

25.0

0.0 0.9 0.1 0.7

1.1

Yes

N/A

No

N/A

Good N/A

Intersection ID: 5514 Main Street: SUNSET RD **Cross Street: MILHAVEN LN** Location: NE Ramp Type: Directional1 Initial Pass/Fail: Pass **Overall Compliance: No** 15 ADA ID: 300F04E5A21D **Severity Score:**

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

Yes

Yes

N/A

N/A

Yes

Yes

Yes

Data

85.0

56.0

5.2

0.6

N/A No

N/A

No

90.5

60.0

2.0

0.2 No

N/A Yes

No Yes

Compliance Description

Grade Break?

Flare Type RT

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset LT (in)

DWS Offset RT (in)

Flare Traversable RT?

Grade Break Slope (%)

Grade Break XSlope (%)



MILHAVEN LN Street 1 Name Stop Condition-Street 1 Signal Street 2 Name N/A Stop Condition-Street 2 N/A

Possible Solutions:	<u>Co</u>
Remove & Replace Entire Ramp.	N/A
Grind Gutter Lip.	Yes
	Yes
	Yes
	No
	N/A
Surveyor Notes:	N/A
N/A	Yes
	Yes
	Yes
	Yes
PROW/ADA:	N/A
R304.2.3, R305.1.4, R302.7.2	N/A
	Yes
	No
	N/A

, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			· ·			` ,
		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)
		No	Gutter Lip Ht (in)	0.3	Yes	Gutter X Slope (%)
		N/A	Painted X Walk1?	Yes		Road Slope (%)
			X Walk 1 Direction	To W		Road X Slope (%)
			X Walk 1 Width (in)	106.0	l	Clear Space?
			X Walk 1 Slope (%)	0.7	N/A	Clear Space to XWalk (in)
			X Walk 1 X Slope (%)	1.1	Yes	Storm Grate/Utility Hazard?
		Yes	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type
		Yes	Any Obstructions?	No		
Total Cost:	\$ 1800.00		Obstruction Type		Yes	Surface Condition? (G/P)
				N/A	N/A	Curb Slope (%)

mpliance Description

Ramp Length (in)

Ramp Width (in)

Ramp Slope (%)

Flare Type LT

Ramp XSlope (%)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Flare Traversable LT?





