cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 2482	section ID: 24827 Main Street: ARBORETUM_DR		Cross	Cross Street: PINEVILLE-MATTHEWS_RD				Location:	W	
ADA ID: 30246C6E69	9A8 Ramp Type: PerpDiag		Initial F	Initial Pass/Fail: Fail Overall Compliance: N			nce: N	o Severity Score:	35	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:					ta Compliance Description		Data	
		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	With	N/A	Ramp Length (in)	59.0	No	Ramp Slope (%)	13.6	
			••••	No	Ramp Width (in)	42.0	No	Ramp XSlope (%)	2.1	
				N/A	Flare Type LT	N/A		Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	Ken B			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
NO 10 M				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
11/2/10		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
PROW/ADA: R304.5.1, R304.2.2, R304.5.3				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N004.0.1, N004.2.2, N004.0.0				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
So all the second se					X Walk 1 Direction	To SE		X Walk 2 Direction	To NE	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	PINEVILLE-MATTHEWS RD	-			X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	3.1	
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	3.2		X Walk 2 X Slope (%)	0.2	
Street 2 Name	ARBORETUM DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	StopSign				Road Slope (%)	2.4	N/A	Clear Space?	N/A	
					Road X Slope (%)	2.3	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type		
					••	N/A			N/A	
							1			

Yes Surface Condition? (G/P)

Good

