

## **Access Compliance Report** Public Rights-of-Way (Curb Ramps)



Intersection ID: 12633	Main Street: BERRYHILL_RD				Cross Street: WILKINSON_BV				Location: SW	
ADA ID: 3074F87F6EAC	Ramp Type: Combination1				Initial Pass/Fail: Fail Overall Complian			ce: No Severity Score: 25		25
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:			Compliance Description		Data Compliance Description			Data
		Remove & Replace	Entire Ran	np.	N/A	Ramp Length LT (in)	60.0	N/A	Ramp Length RT (in)	60.0
				··P·	Yes	Ramp Width LT (in)	60.0	Yes	Ramp Width RT (in)	60.0
	GE				Yes	Ramp Slope LT (%)	3.9	No	Ramp Slope RT (%)	11.0
	1				No	Ramp XSlope LT (%)	3.4	No	Ramp XSlope RT (%)	5.2
WILKINSON_BV	-				N/A	Ramp Length (in)	57.0	Yes	Ramp Slope (%)	8.0
					Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	6.4
Lungana -		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
ter	A. A.	LT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	12 100				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	Tak at	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	TRANS.	Not Found, R304.5.	3 R304 3 2	,	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	14 10 10 10 10		0,1004.012		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	ALL IN				N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	StopSign				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	BERRYHILL RD				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A					X Walk 1 Direction	To E		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	2.2		X Walk 2 Slope (%)	N/A
						X Walk 1 X Slope (%)	9.0		X Walk 2 X Slope (%)	N/A
		Total Cost:	\$	1800.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	N/A		Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					the second			N/A	Any Obstruction?	N/A
		A AR			a case				Obstruction Type	
	The second second			and and the	1. 10. AN					N/A
the second secon								N/A	Storm Grate/Utility Hazard?	N/A
		1-		1 A P	Manufal				Storm Grate/Utility Type	IN/A

Storm Grate/Utility Type N/A Surface Condition? (G/P) Yes Good Curb Slope (%) 11.2





