cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Surface Condition? (G/P)

Curb Slope (%)

Good

18.5

Yes

			<u>`</u>	. ,					
Intersection ID: 10615	Main Street: SPRATT_ST			Cross Street: POLK_ST			Location: NE		NE
ADA ID: 30847390DA74	Ramp Type: Combination2			Initial Pass/Fail: Fail Overall Complian			nce: No Severity Score: 21.25		21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data
16	The second	Remove & Replace Er	tire Ramp.	N/A	Ramp Length LT (in)	55.5	N/A	Ramp Length RT (in)	30.0
			•	N/A	Ramp Width LT (in)	43.0	No	Ramp Width RT (in)	45.0
	All A			N/A	Ramp Slope LT (%)	4.0	Yes	Ramp Slope RT (%)	6.8
				N/A	Ramp XSlope LT (%)	5.8	No	Ramp XSlope RT (%)	3.2
	A Side			N/A	Ramp Length (in)	67.0	Yes	Ramp Slope (%)	7.2
the Alexandree				No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	2.7
8/ E	And Car	Surveyor Notes:		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
K C		LT RP < 5%		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	ANN?			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A A A				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	TOP			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	the second	PROW/ADA:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
A AND AND AND AND AND AND AND AND AND AN	- AL-	Not Found, R304.5.1,	R304.5.1.	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
16 the	1 Blacks	R304.5.3	· · · ,	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	StopSign			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	SPRATT ST			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A				X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	2.3		X Walk 2 Slope (%)	N/A
					X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	N/A
		Total Cost:	\$ 160	0.00 N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
					Road Slope (%)	N/A		Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				Constant and			N/A	Any Obstruction?	N/A
		and the second s	the making		a south a			Obstruction Type	
	-								N/A
							N/A	Storm Grate/Utility Hazard?	N/A
					the second			Storm Grate/Utility Type	11/5
The second second									N/A