

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



			•	. ,						
Intersection ID: 46663	Main Stre	Cross Street: N_DAVIDSON_ST					Location: SE			
ADA ID: 310188DE6C93	Ramp Ty	Ramp Type: Combination1			Initial Pass/Fail: Fail Overall Complia			nce: No Severity Score: 22		22.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:			Compliance Description			Data Compliance Description		
	E.	Remove & Replace Er	ntire Ramp.	N/A	Ramp Leng	gth LT (in)	144.0	N/A	Ramp Length RT (in)	122.0
				Yes	Ramp Widt		71.0	Yes	Ramp Width RT (in)	72.0
The second second	and the state			No	Ramp Slop	be LT (%)	8.4	No	Ramp Slope RT (%)	8.6
	1.			No	Ramp XSI	ope LT (%)	2.1	No	Ramp XSlope RT (%)	2.5
	X			N/A	Ramp Leng	gth (in)	48.0	No	Ramp Slope (%)	8.6
	51			No	Ramp Width (in)		43.0	No	Ramp XSlope (%)	2.8
NEDAMIDSON	States State	Surveyor Notes:		N/A	Flare Type	LT	N/A	N/A	Flare Type RT	N/A
the second secon	······································	N/A		N/A	Flare Slop	e LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
6. · · · · · · · · · · · · · · · · · · ·				N/A	Flare Trave	ersable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Le	ength (in)	N/A	N/A	DWS Provided?	N/A
	4410			N/A	Landing W	idth (in)	N/A	N/A	DWS Contrast?	N/A
		PROW/ADA:		N/A	Landing Sl	ope (%)	N/A	N/A	DWS Length (in)	N/A
E PAR	ARD A	Not Found, R304.5.1, R304.2.2,		N/A	Landing X	Slope (%)	N/A	N/A	DWS Full Width?	N/A
		R304.5.3, R304.3.2	,	N/A	Landing Cu	urb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared La	nding?	N/A			
		N/A	Gutter Ponding?		N/A	N/A	Gutter Slope (%)	N/A		
Street 1 Name	StopSign			N/A	Gutter Lip	Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	DONATELLO AV			N/A	Painted X	Walk1?	No	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A				X Walk 1 D	Direction	To W		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A				X Walk 1 V	Vidth (in)	N/A		X Walk 2 Width (in)	N/A
					X Walk 1 S	lope (%)	2.2		X Walk 2 Slope (%)	N/A
					X Walk 1 X	( Slope (%)	1.4		X Walk 2 X Slope (%)	N/A
		Total Cost:	\$ 180	0.00 N/A	Ramp insid	de XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
					Road Slope	e (%)	N/A		Clear Space?	N/A
					Road X Slo	ope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		Donatello 📷		Ano		9		N/A	Any Obstruction?	N/A
RENAISSANCE				AND DR. ARA	A A A A A A A A A A A A A A A A A A A				Obstruction Type	
										N/A
				States				N/A	Storm Grate/Utility Hazard?	N/A

 N/A
 Storm Grate/Outry Trazard ?
 N/A

 Storm Grate/Utility Type
 N/A

 Yes
 Surface Condition? (G/P)
 Good

 Curb Slope (%)
 33.5





