


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: N/A	Main Street: IDLEWILD_RD	Cross Street: E_INDEPENDENCE_RA	Location: SE
ADA ID: 313D03FE1E23	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: No
			Severity Score: 10.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		<b>Compliance</b>	<b>Description</b>	<b>Data</b>
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	65.0
	Remove & Replace Gutter.		Yes	Ramp Width (in)	59.5
			N/A	Flare Type LT	Sloped
			N/A	Flare Slope LT (%)	13.4
			N/A	Flare Traversable LT?	Yes
			Yes	Landing Length (in)	69.0
			Yes	Landing Width (in)	61.0
			Yes	Landing Slope (%)	0.7
			Yes	Landing X Slope (%)	2.3
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.2.3, R304.5.4, R304.5.3</p>			N/A	Flare Type RT	N/A
			Yes	Flare Slope RT (%)	5.6
			N/A	Flare Traversable RT?	Yes
			Yes	DWS Provided?	Yes
			Yes	DWS Contrast?	Yes
			Yes	DWS Length (in)	24.0
			Yes	DWS Full Width?	Yes
			N/A	DWS Offset (in)	0.0
			N/A	Gutter Slope (%)	5.2
			N/A	Gutter X Slope (%)	8.9
<p>Total Cost:</p> <p>\$ 2600.00</p>			No	Painted X Walk1?	N/A
			No	Painted X Walk2?	N/A
			To N	X Walk 1 Direction	N/A
			N/A	X Walk 2 Direction	N/A
			N/A	X Walk 1 Width (in)	N/A
			N/A	X Walk 2 Width (in)	N/A
			7.3	X Walk 1 Slope (%)	N/A
			8.2	X Walk 2 Slope (%)	N/A
			N/A	X Walk 1 X Slope (%)	N/A
			N/A	X Walk 2 X Slope (%)	N/A
<p>Street 1 Name</p> <p>IDLEWILD RD</p> <p>Stop Condition-Street 2</p> <p>Signal</p> <p>Street 2 Name</p> <p>N/A</p> <p>Stop Condition-Street 1</p> <p>N/A</p>			N/A	Ramp inside XWalk1?	N/A
			N/A	Ramp inside XWalk2?	N/A
			N/A	Road Slope (%)	Yes
			N/A	Road X Slope (%)	N/A
			Yes	Clear Space?	Yes
			No	Clear Space to XWalk (in)	N/A
			Yes	Storm Grate/Utility Hazard?	No
				Storm Grate/Utility Type	
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good

