

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A	Main Str	eet: YORK_CENTER	Cross	Street	N/A	Location:	SW		
				Cross Street: N/A					
ADA ID: 315510A24022 Ramp Type: Directional2			Initia	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	A THE	Possible Solutions:		Compliance Description			Data Compliance Description		
	D	Remove & Replace Entire Rar	np.	N/A	Ramp Length (in)	80.0	N/A	Grade Break?	N/A
				Yes	Ramp Width (in)	50.0	N/A	Grade Break Slope (%)	0.0
AT AN ALS THE PLAN				No	Ramp Slope (%)	8.5	N/A	Grade Break XSlope (%)	0.0
A SALE NO				Yes	Ramp XSlope (%)	1.1			
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
WHITEHALL COMMONS CENT				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
t. t.		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	No.	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
	in Yes			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
and the second	A	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
A A A A A A A A A A A A A A A A A A A		R304.2.2		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
	the street of			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
A Free Contraction				N/A	Painted X Walk1?	No		Road Slope (%)	0.9
Street 1 Name WHITEHALL COMMONS CENTER DR					X Walk 1 Direction	To E		Road X Slope (%)	2.8
Stop Condition-Street 1	None				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	0.9	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	2.8	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1800.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	0.7

