

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 5741	Main Street: MALLARD_CREEK_RD	Cross Street: NEVIN_RD	Location: NE
ADA ID: 3169FDAD2CA2	Ramp Type: MedianPerp	Initial Pass/Fail: Pass	Overall Compliance: No
			Severity Score: 2.5

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)	7.4
			Yes	Ramp Width (in)	56.0	Yes	Ramp XSlope (%)	0.8
			Yes	Flare Type L	Curbed_NoWalkSurface	Yes	Flare Type RT	N/A
			Yes	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
			Yes	Landing Length (in)	88.0	Yes	DWS Provided?	Yes
			Yes	Landing Width (in)	56.0	Yes	DWS Contrast?	Yes
			Yes	Landing Slope (%)	0.6	Yes	DWS Length (in)	24.0
			Yes	Landing X Slope (%)	0.7	No	DWS Full Width?	No
Surveyor Notes:	N/A		N/A	Landing Curb? (Y/N)	N/A	Yes	DWS Offset (in)	0.0
			N/A	Shared Landing?	Yes			
			Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.0
			Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.4
			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
			N/A	X Walk 1 Width (in)	125.0	N/A	X Walk 2 Width (in)	N/A
				X Walk 1 Slope (%)	1.4		X Walk 2 Slope (%)	N/A
				X Walk 1 X Slope (%)	1.1		X Walk 2 X Slope (%)	N/A
			Yes	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
PROW/ADA:	Not Found, R305.1.4			Road Slope (%)	N/A	N/A	Clear Space?	Yes
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
				Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A
						Yes	Surface Condition? (G/P)	Good
Total Cost:		\$ 1650.00						

Street 1 Name	NEVIN RD
Stop Condition-Street 2	Signal
Street 2 Name	N/A
Stop Condition-Street 1	N/A

