

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10040568 Main Street: W_ARROWOOD_RD				Cross Street: N/A				Location:	SE
ADA ID: 31AF1674D736 Ramp Type: PerpDiag			Initial P	nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	10.01	Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data
THE		Remove & Replace Curb Ramp W	lith	N/A	Ramp Length (in)	62.0	No	Ramp Slope (%)	9.3
The state		Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	2.6
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
THE CONTRACT	ED /			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
A The second	Delter.			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
WL ARTSO	1 HOLEN			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	· · · · · · · · ·	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	A Start	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
<mark>b.</mark>	- Barbaran -			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
the the the second	a F ERGE			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
2				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		20 July - 20 Jul		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	22 3				X Walk 1 Direction	To N		X Walk 2 Direction	To W
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	W ARROWOOD RD				X Walk 1 Slope (%)	3.4		X Walk 2 Slope (%)	1.4
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	2.8		X Walk 2 X Slope (%)	2.5
Street 2 Name	ENTRANCE			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	4.0	N/A	Clear Space?	N/A
					Road X Slope (%)	5.5	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

