## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 46375	Main Str	Main Street: HONOR_GUARD_AV			Cross Street: ROYAL_CASTLE_CT				NW
ADA ID: 31DEEE1EE9E5	Ramp Ty	Ramp Type: PerpDiag			ail: Fail Overall C	o Severity Score:	21.25		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	Possible Solutions:		Compliance Description			Data Compliance Description			
LIONOR_GUARD_AV		Remove & Replace Curb Ramp	Mith	N/A	Ramp Length (in)	49.0	Yes	Ramp Slope (%)	<u>Data</u> 7.5
		Two New Directional Ramps or		No	Ramp Width (in)	38.0	No	Ramp XSlope (%)	6.4
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A N/A
		Current Middae		N/A		N/A	N/A	DWS Provided?	N/A N/A
					Landing Length (in)				
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A		DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
the second second				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Strange Transformer				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
1 - Channel		R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
and a state of the	14			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
A STATE OF A	The second second				X Walk 1 Direction	To S		X Walk 2 Direction	To E
the New York The Party of the	The second second			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	HONOR GUARD AV				X Walk 1 Slope (%)	5.1		X Walk 2 Slope (%)	1.6
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	3.8
Street 2 Name	ROYAL CASTLE CT			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	6.4	N/A	Clear Space?	N/A
	10116				Road X Slope (%)	0. <del>4</del> 1.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	,		N/A	• • • • •	N/A N/A
		T-1-1-0		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

