


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 10041631	Main Street: WHITEHALL_PARK_DR	Cross Street: N/A	Location: SE
ADA ID: 321592D5B60C	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	
Severity Score: 8.75			

	<b>Possible Solutions:</b>							
	<b>Remove &amp; Replace Curb Ramp With Two New Directional Ramps or Equivalent.</b>		<b>Compliance</b>	<b>Description</b>	<b>Data</b>	<b>Compliance</b>	<b>Description</b>	<b>Data</b>
	<b>N/A</b>	Ramp Length (in)	<b>55.0</b>	<b>Yes</b>	Ramp Slope (%)	<b>5.5</b>		
	<b>No</b>	Ramp Width (in)	<b>43.0</b>	<b>Yes</b>	Ramp XSlope (%)	<b>0.9</b>		
	<b>N/A</b>	Flare Type LT	<b>N/A</b>	<b>N/A</b>	Flare Type RT	<b>N/A</b>		
	<b>N/A</b>	Flare Slope LT (%)	<b>N/A</b>	<b>N/A</b>	Flare Slope RT (%)	<b>N/A</b>		
	<b>N/A</b>	Flare Traversable LT?	<b>N/A</b>	<b>N/A</b>	Flare Traversable RT?	<b>N/A</b>		
	<b>N/A</b>	Landing Length (in)	<b>N/A</b>	<b>N/A</b>	DWS Provided?	<b>N/A</b>		
	<b>N/A</b>	Landing Width (in)	<b>N/A</b>	<b>N/A</b>	DWS Contrast?	<b>N/A</b>		
	<b>N/A</b>	Landing Slope (%)	<b>N/A</b>	<b>N/A</b>	DWS Length (in)	<b>N/A</b>		
<p>Surveyor Notes:</p> <p><b>N/A</b></p> <p>PROW/ADA:</p> <p><b>R304.5.1</b></p>	<b>N/A</b>	Landing X Slope (%)	<b>N/A</b>	<b>N/A</b>	DWS Full Width?	<b>N/A</b>		
	<b>N/A</b>	Landing Curb? (Y/N)	<b>N/A</b>	<b>N/A</b>	DWS Offset (in)	<b>N/A</b>		
	<b>N/A</b>	Shared Landing?	<b>N/A</b>					
	<b>N/A</b>	Gutter Ponding?	<b>N/A</b>	<b>N/A</b>	Gutter Slope (%)	<b>N/A</b>		
	<b>N/A</b>	Gutter Lip Ht (in)	<b>N/A</b>	<b>N/A</b>	Gutter X Slope (%)	<b>N/A</b>		
	<b>N/A</b>	Painted X Walk1?	<b>No</b>	<b>N/A</b>	Painted X Walk2?	<b>No</b>		
		X Walk 1 Direction	<b>To NW</b>		X Walk 2 Direction	<b>To SW</b>		
	<b>N/A</b>	X Walk 1 Width (in)	<b>N/A</b>	<b>N/A</b>	X Walk 2 Width (in)	<b>N/A</b>		
		X Walk 1 Slope (%)	<b>0.3</b>		X Walk 2 Slope (%)	<b>7.0</b>		
		X Walk 1 X Slope (%)	<b>0.5</b>		X Walk 2 X Slope (%)	<b>3.0</b>		
<p>Street 1 Name</p> <p><b>ENTRANCE</b></p> <p>Stop Condition-Street 2</p> <p><b>StopSign</b></p> <p>Street 2 Name</p> <p><b>WHITEHALL PARK DR</b></p> <p>Stop Condition-Street 1</p> <p><b>None</b></p>	<b>N/A</b>	Ramp inside XWalk1?	<b>N/A</b>	<b>N/A</b>	Ramp inside XWalk2?	<b>N/A</b>		
		Road Slope (%)	<b>3.2</b>	<b>N/A</b>	Clear Space?	<b>N/A</b>		
		Road X Slope (%)	<b>0.4</b>	<b>N/A</b>	Clear Space to XWalk (in)	<b>N/A</b>		
	<b>N/A</b>	Any Obstructions?	<b>N/A</b>	<b>N/A</b>	Storm Grate/Utility Hazard?	<b>N/A</b>		
		Obstruction Type			Storm Grate/Utility Type			
			<b>N/A</b>			<b>N/A</b>		
				<b>Yes</b>	Surface Condition? (G/P)	<b>Good</b>		
Total Cost:		<b>\$</b>	<b>3200.00</b>					

