

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 3512 Main Stu	Main Street: BALATA_CT		Cross Street: SAWGRASS_RIDGE_PL				SE
	Ramp Type: Perp		Initial Pass/Fail: Fail Overall Compliance:			Location: o Severity Score:	42.5
· · · ·						42.5	
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance					
	Possible Solutions:	Com	bliance Description			liance Description	Data
	Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	50.0	No	Ramp Slope (%)	8.4
	4	No	Ramp Width (in)	34.0	No	Ramp XSlope (%)	5.7
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
ANTIGENES RIDES PL		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
9AWGRASS LADOL	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
E b	N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	80 	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	7	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		N/A	Shared Landing?	N/A			
	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	R304.5.1, R304.2.2, R304.5.3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	8	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
The second secon			X Walk 1 Direction	To W		X Walk 2 Direction	N/A
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name BALATA CT			X Walk 1 Slope (%)	5.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 StopSign			X Walk 1 X Slope (%)	1.3		X Walk 2 X Slope (%)	N/A
Street 2 Name N/A		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 N/A			Road Slope (%)	N/A	N/A	Clear Space?	N/A
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 1	850.00	Obstruction Type			Storm Grate/Utility Type	
				N/A			N/A

Yes Surface Condition? (G/P)

Good

