

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



							_			
Intersection ID: 11842	ID: 11842 Main Street: CAGLE_AV			Cross Street: N_SHARON_AMITY_RD				Location:	SE	
ADA ID: 325D06C37091	A ID: 325D06C37091 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	The second second	Possible Solutions:		Compliance Description Data			Compliance Description		Data	
Date Kined	Elle Mark	Remove & Replace B	Entire Ramp		N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	9.1
	Ser Land	·	•		No	Ramp Width (in)	41.0	Yes	Ramp XSlope (%)	1.7
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		-			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	CAGLELAD				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	- interest				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
5		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	a v That and				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	a later and				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	State of the second second				N/A	Shared Landing?	N/A			
A VS		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
18 3	Provent and	Not Found, R304.5.	1. R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	All a	,			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
						X Walk 1 Direction	To W		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	N SHARON AMITY RD					X Walk 1 Slope (%)	2.4		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	<b>\$</b> 1	850.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

Yes Surface Condition? (G/P)

Good

