

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

39.5

59.5

11.9

1.0

7.6

6.6

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Main Street: GARNETTE PL Intersection ID: 8552 **Cross Street: MITCHELL ST** Location: SW Initial Pass/Fail: Fail **Overall Compliance: No** 25 ADA ID: 326943968EC4 Ramp Type: Combination2 **Severity Score:** 

Compliance Description

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)

N/A

N/A

N/A

N/A

N/A

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A N/A

N/A

N/A

N/A

**Codes/Mitigation Info/Possible Solution** 

## **Field Measurements/Component Compliance**

N/A

Yes

No

Yes

Yes

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

Flare Traversable RT?

Flare Type RT

Data

N/A

N/A

N/A

N/A

48.5

43.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A



Street 1 Name Signal MITCHELL ST Stop Condition-Street 1 Street 2 Name N/A Stop Condition-Street 2 N/A Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.5.3, R304.3.2



Total Cost:



1600.00

Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Shared Landing?	N/A			
Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
X Walk 1 Direction	To E		X Walk 2 Direction	N/A
X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
X Walk 1 Slope (%)	4.2		X Walk 2 Slope (%)	N/A
X Walk 1 X Slope (%)	0.6		X Walk 2 X Slope (%)	N/A
Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Road Slope (%)	N/A		Clear Space?	N/A
Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstruction?	N/A
			Obstruction Type	
				N/A
1000		N/A	Storm Grate/Utility Hazard?	N/A
The second second			Storm Grate/Utility Type	1071
				N/A
A		Yes	Surface Condition? (G/P)	Good
			Curb Slope (%)	27.1