


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 15174		Main Street: DILWORTH_RD_WEST		Cross Street: IDEAL_WY		Location: NW																							
ADA ID: 32F2D1E8D81D		Ramp Type: Directional1		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 1.25																					
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance																								
 <div>Street 1 NameDILWORTH RD WEST</div> <div>Stop Condition-Street 1StopSign</div> <div>Street 2 NameN/A</div> <div>Stop Condition-Street 2N/A</div>					Possible Solutions:					ComplianceDescriptionDataComplianceDescriptionData																			
					Remove & Replace Entire Ramp.					N/A					Ramp Length (in)32.0					N/A					Grade Break?N/A				
Surveyor Notes:					N/A					Yes					Ramp Width (in)60.0					N/A					Grade Break Slope (%)0.0				
					PROW/ADA:					R304.5.3					Yes					Ramp Slope (%)5.1					N/A				
Total Cost:										\$1600.00					No					Ramp XSlope (%)2.4					N/A				
															N/A					Flare Type RTN/A					N/A				
															N/A					Flare Slope RT (%)N/A					N/A				
															N/A					Flare Traversable RT?N/A					N/A				
															N/A					Landing Width (in)0.0					N/A				
															N/A					Landing Slope (%)0.0					N/A				
															N/A					Landing X Slope (%)0.0					N/A				
															N/A					Landing X Slope (%)0.0					N/A				
															N/A					Landing Curb? (Y/N)N/A					N/A				
															N/A					Shared Landing?N/A					N/A				
															N/A					Gutter Ponding?0.0					N/A				
															N/A					Gutter Lip Ht (in)0.0					N/A				
															N/A					Painted X Walk1?No					Road Slope (%)6.8				
																				X Walk 1 DirectionTo NE					Road X Slope (%)0.6				
																				X Walk 1 Width (in)N/A					Clear Space?N/A				
																				X Walk 1 Slope (%)6.8					N/A				
																				X Walk 1 X Slope (%)0.6					N/A				
															N/A					Ramp inside XWalk1?N/A					Storm Grate/Utility Type				
															N/A					Any Obstructions?N/A					N/A				
																				Obstruction TypeYes					Surface Condition? (G/P)Good				
																				N/A					N/A				