## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 28870 Main Str	Cross Street: SHOPTON_RD					Location:	SW	
ADA ID: 33BA2C16D3FC Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliance: No				Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
Possible Solutions:		C				liance Description	Data	
STREET BALLAR GE	Remove & Replace Curb Ramp W	ith N	N/A	Ramp Length (in)	95.0	No	Ramp Slope (%)	10.3
	Two New Directional Ramps or Equivalent.		/es	Ramp Width (in)	50.0	No	Ramp XSlope (%)	4.7
		N	I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		Ν	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		Ν	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		Ν	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:	Ν	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	Ν	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		Ν	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		Ν	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		Ν	N/A	Shared Landing?	N/A			
	PROW/ADA:	Ν	I/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.2.2, R304.5.3		I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		Ν	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
A A A A A A A A A A A A A A A A A A A				X Walk 1 Direction	To E		X Walk 2 Direction	To N
		Ν	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name ARYSHIRE GLEN PL	-			X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	3.6
Stop Condition-Street 2 StopSign				X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	3.9
Street 2 Name SHOPTON RD		Ν	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 None				Road Slope (%)	5.1	N/A	Clear Space?	N/A
				Road X Slope (%)	2.1	N/A	Clear Space to XWalk (in)	N/A
		Ν	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 32	00.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A