

Access Compliance Report Public Rights-of-Way (Curb Ramps)



					(Landers	-		
Intersection ID: 11987	Main Sti	Main Street: AIRLIE_ST			eet:	COUNTRY_CLUB_DR	Location:	E		
ADA ID: 33D62CEEDC4A	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance:				ice: N	o Severity Score:	22.5
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance							
		Possible Solutions:		Compliance Description D			Data	ata Compliance Description		
		Remove & Replace E	ntire Ramp.	N	/ A	Ramp Length (in)	60.0	No	Ramp Slope (%)	9.0
		· ·	•	N	0	Ramp Width (in)	42.0	No	Ramp XSlope (%)	2.3
	The second			N/	Α/	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	3			N	/ A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	" Hellen			N	/ A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N	/ A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
COUNTRAL COURS DO	" and the second	Surveyor Notes:		N	/ A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	1 25	N/A		N	/ A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	9 20 Mar			N	/ A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	- Pri			N	/ A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	E-			N	/ A	Shared Landing?	N/A			
A Partiller		PROW/ADA:		N	/ A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1	. R304.2.2.	N/	/ A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	N/A
		R304.5.3	,,	N	/ A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
and the second second	States of the					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
				N	/ A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	AIRLIE ST					X Walk 1 Slope (%)	5.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	3.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N	/ A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N	/ A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$1	850.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

Yes Surface Condition? (G/P)

Good

