


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 26441	Main Street: GRABURN_RD	Cross Street: JOHNSTON_RD	Location: SW
ADA ID: 33F313F25E01	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 13.75

Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance			
 <p>Street 1 Name                      <b>JOHNSTON RD</b></p> <p>Stop Condition-Street 2                      <b>None</b></p> <p>Street 2 Name                      <b>GRABURN RD</b></p> <p>Stop Condition-Street 1                      <b>StopSign</b></p>	<p>Possible Solutions:</p> <p><b>Remove &amp; Replace Curb Ramp With Two New Directional Ramps or Equivalent.</b></p> <p>Surveyor Notes:</p> <p><b>N/A</b></p> <p>PROW/ADA:</p> <p><b>Not Found, R304.2.2, R304.5.3</b></p>	<p><b>Compliance</b>   <b>Description</b>   <b>Data</b></p> <p>N/A   Ramp Length (in)   <b>60.0</b></p> <p>Yes   Ramp Width (in)   <b>49.0</b></p> <p>N/A   Flare Type LT   <b>N/A</b></p> <p>N/A   Flare Slope LT (%)   <b>N/A</b></p> <p>N/A   Flare Traversable LT?   <b>N/A</b></p> <p>N/A   Landing Length (in)   <b>N/A</b></p> <p>N/A   Landing Width (in)   <b>N/A</b></p> <p>N/A   Landing Slope (%)   <b>N/A</b></p> <p>N/A   Landing X Slope (%)   <b>N/A</b></p> <p>N/A   Landing Curb? (Y/N)   <b>N/A</b></p> <p>N/A   Shared Landing?   <b>N/A</b></p> <p>N/A   Gutter Ponding?   <b>N/A</b></p> <p>N/A   Gutter Lip Ht (in)   <b>N/A</b></p> <p>N/A   Painted X Walk1?   <b>No</b></p> <p>         X Walk 1 Direction   <b>To NE</b></p> <p>N/A   X Walk 1 Width (in)   <b>N/A</b></p> <p>         X Walk 1 Slope (%)   <b>3.4</b></p> <p>         X Walk 1 X Slope (%)   <b>0.5</b></p> <p>N/A   Ramp inside XWalk1?   <b>N/A</b></p> <p>         Road Slope (%)   <b>1.8</b></p> <p>         Road X Slope (%)   <b>3.1</b></p> <p>N/A   Any Obstructions?   <b>N/A</b></p> <p>         Obstruction Type   <b>N/A</b></p>	<p><b>Compliance</b>   <b>Description</b>   <b>Data</b></p> <p>No   Ramp Slope (%)   <b>9.0</b></p> <p>No   Ramp XSlope (%)   <b>4.5</b></p> <p>N/A   Flare Type RT   <b>N/A</b></p> <p>N/A   Flare Slope RT (%)   <b>N/A</b></p> <p>N/A   Flare Traversable RT?   <b>N/A</b></p> <p>N/A   DWS Provided?   <b>N/A</b></p> <p>N/A   DWS Contrast?   <b>N/A</b></p> <p>N/A   DWS Length (in)   <b>N/A</b></p> <p>N/A   DWS Full Width?   <b>N/A</b></p> <p>N/A   DWS Offset (in)   <b>N/A</b></p> <p>N/A   Gutter Slope (%)   <b>N/A</b></p> <p>N/A   Gutter X Slope (%)   <b>N/A</b></p> <p>N/A   Painted X Walk2?   <b>No</b></p> <p>         X Walk 2 Direction   <b>To NW</b></p> <p>N/A   X Walk 2 Width (in)   <b>N/A</b></p> <p>         X Walk 2 Slope (%)   <b>1.5</b></p> <p>         X Walk 2 X Slope (%)   <b>4.0</b></p> <p>N/A   Ramp inside XWalk2?   <b>N/A</b></p> <p>N/A   Clear Space?   <b>N/A</b></p> <p>N/A   Clear Space to XWalk (in)   <b>N/A</b></p> <p>N/A   Storm Grate/Utility Hazard?   <b>N/A</b></p> <p>         Storm Grate/Utility Type   <b>N/A</b></p> <p>N/A   Surface Condition? (G/P)   <b>Good</b></p>		
	Total Cost:	\$	3200.00		

