

Access Compliance Report Public Rights-of-Way (Curb Ramps)



					/							
Intersection ID: 52149 Main Street: OLD_ARDREY_KELL_RD				Cross	Cross Street: ARDREY_PLACE_DR				Location:	SE		
ADA ID: 33FA34FE8FB7	7 Ramp Ty	Ramp Type: Combination1			Initial Pass/Fail: Fail Overall Complian				o Severity Score:	25		
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance												
		Possible Solutions:			Comp	liance Description			liance Description	Data		
		Remove & Replace Ent	ire Ram	D.	N/A	Ramp Length LT (in)	76.0	N/A	Ramp Length RT (in)	80.0		
					Yes	Ramp Width LT (in)	48.0	Yes	Ramp Width RT (in)	48.0		
the state of the s					Yes	Ramp Slope LT (%)	8.3	No	Ramp Slope RT (%)	12.3		
					Yes	Ramp XSlope LT (%)	1.9	Yes	Ramp XSlope RT (%)	1.7		
	3 9 8				N/A	Ramp Length (in)	44.0	Yes	Ramp Slope (%)	5.3		
					Yes	Ramp Width (in)	49.0	Yes	Ramp XSlope (%)	0.5		
ARDREY PLACE		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
the second secon	LANY LE	N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
	The second				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
	ICARP				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
		PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
		R304.3.2			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
The second se	and - a line				N/A	Shared Landing?	N/A					
	1 and the second				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
Street 1 Name	None				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
Stop Condition-Street 1	OLD ARDREY KELL RD				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
Street 2 Name	N/A					X Walk 1 Direction	To W		X Walk 2 Direction	N/A		
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A		
						X Walk 1 Slope (%)	4.4		X Walk 2 Slope (%)	N/A		
						X Walk 1 X Slope (%)	0.3		X Walk 2 X Slope (%)	N/A		
		Total Cost:	\$	1800.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
						Road Slope (%)	N/A		Clear Space?	N/A		
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
							N/A	Any Obstruction?	N/A			
									Obstruction Type	N/A		

N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A

Yes	Surface Condition? (G/P)	Good	
	Curb Slope (%)	3.3	





