cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10123	Main Street: GLENWOOD DR				root		Location:	NW		
Intersection ID: 10123	Main Street: GLENWOOD_DR			Cross Street: TUCKASEEGEE_RD						
ADA ID: 3477A488A8FC Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10		
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance							
		Possible Solutions:	ble Solutions:		Compliance Description			Data Compliance Description		
	and allow a	Remove & Replace	Entire Ramp.		N/A	Ramp Length (in)	63.0	Yes	Ramp Slope (%)	8.0
	The second				No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	3.8
	- 117			I	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
A Company and the second secon	1310 9	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
TUOKASEEGE		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	and the second				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
E.	Contraction of				N/A	Shared Landing?	N/A			
6.	A NOR	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.	1. R304.5.3	1	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	14. (A)	,	,		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
						X Walk 1 Direction	To S		X Walk 2 Direction	N/A
1 The second of					N/A	X Walk 1 Width (in)	114.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name TUCKAS	EEGEE RD					X Walk 1 Slope (%)	7.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	Signal					X Walk 1 X Slope (%)	0.6		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 1	850.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

Yes Surface Condition? (G/P)

Good

