## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

| Intersection ID: 10027410               | tersection ID: 10027410 Main Street: GOLF_ACRES_DR |                              |         | Street:  | N/A                   | Location:                   | SE  |                             |      |
|---|--|------------------------------|---------|--|-----------------------|-----------------------------|-----|-----------------------------|------|
| ADA ID: 3486C8944B89                    | 3486C8944B89 Ramp Type: PerpDiag                   |                              |         | Initial Pass/Fail: Fail Overall Compliance: No |                       |                             |     | o Severity Score:           | 8.75 |
| Codes/Mitigation Info/Possible Solution |  |                              |         | Field Measurements/Component Compliance        |                       |                             |     |                             |      |
|   | and the second                                     | Possible Solutions:          |         | Compliance Description                         |                       | Data Compliance Description |     | Data                        |      |
|   |  | Remove & Replace Curb Ramp   | With    | N/A  | Ramp Length (in)      | 48.0                        | Yes | Ramp Slope (%)              | 6.3  |
|   |  | Two New Directional Ramps or |         | No   | Ramp Width (in)       | 44.0                        | Yes | Ramp XSlope (%)             | 1.6  |
| the second second                       |  | Equivalent.                  |         | N/A  | Flare Type LT         | N/A                         | N/A | Flare Type RT               | N/A  |
| South States                            |  |                              |         | N/A  | Flare Slope LT (%)    | N/A                         | N/A | Flare Slope RT (%)          | N/A  |
| <u> </u>                                | and the sta  |                              |         | N/A  | Flare Traversable LT? | N/A                         | N/A | Flare Traversable RT?       | N/A  |
| COLF_AGRES DR                           |  |                              |         | N/A  | Landing Length (in)   | N/A                         | N/A | DWS Provided?               | N/A  |
|   | <u></u>  | Surveyor Notes:              |         | N/A  | Landing Width (in)    | N/A                         | N/A | DWS Contrast?               | N/A  |
| K K N/A                                 |  |                              |         | N/A  | Landing Slope (%)     | N/A                         | N/A | DWS Length (in)             | N/A  |
|   |  |                              |         | N/A  | Landing X Slope (%)   | N/A                         | N/A | DWS Full Width?             | N/A  |
|   |  |                              |         | N/A  | Landing Curb? (Y/N)   | N/A                         | N/A | DWS Offset (in)             | N/A  |
| A REAL PROPERTY OF                      |  |                              |         | N/A  | Shared Landing?       | N/A                         |     |                             |      |
| and the second second                   |  | PROW/ADA:                    |         | N/A  | Gutter Ponding?       | N/A                         | N/A | Gutter Slope (%)            | N/A  |
| Not Found, R304.5.1                     |  |                              |         | N/A  | Gutter Lip Ht (in)    | N/A                         | N/A | Gutter X Slope (%)          | N/A  |
|   |  |                              |         | N/A  | Painted X Walk1?      | No                          | N/A | Painted X Walk2?            | No   |
|   |  |                              |         |  | X Walk 1 Direction    | To N                        |     | X Walk 2 Direction          | To W |
|   |  |                              |         | N/A  | X Walk 1 Width (in)   | N/A                         | N/A | X Walk 2 Width (in)         | N/A  |
| Street 1 Name                           | GOLF ACRES DR                                      | -                            |         |  | X Walk 1 Slope (%)    | 1.2                         |     | X Walk 2 Slope (%)          | 2.7  |
| Stop Condition-Street 2                 | None   |                              |         |  | X Walk 1 X Slope (%)  | 0.2                         |     | X Walk 2 X Slope (%)        | 2.4  |
| Street 2 Name                           | ENTRANCE   |                              |         | N/A  | Ramp inside XWalk1?   |                             | N/A | Ramp inside XWalk2?         | N/A  |
| Stop Condition-Street 1                 | StopSign   |                              |         |  | '<br>Road Slope (%)   | 1.2                         | N/A | Clear Space?                | N/A  |
|   |  |                              |         |  | Road X Slope (%)      | 2.1                         | N/A | Clear Space to XWalk (in)   | N/A  |
|   |  |                              |         | N/A  | Any Obstructions?     | N/A                         |     | Storm Grate/Utility Hazard? | N/A  |
|   |  | Total Cost: \$               | 3200.00 |  | Obstruction Type      |                             |     | Storm Grate/Utility Type    |      |
|   |  | · •                          |         |  |                       | N/A                         |     |                             | N/A  |
|   |  |                              |         |  |                       | 1.04                        | 1   |                             |      |

